4/3/2003

**OLYMPIA EXPLORER** 

## DETAILS OF INSPECTION VIOLATIONS CORRECTIVE ACTIONS

NO.	LOCATION	REF.	POINTS	CRITICAL	DESCRIPTION
1	AQUAMARINE DINING ROOM	33	0	No	
SOFT THE	SEALANT WAS USED TO COVE THE JUNCTURE WHERE THE LOWER WAITER STAT	TION CABI	NETS JOINED	THE DECK THE	ROUGHOUT
DINING	G ROOM. SEALANT ORDERED TO REPLACE THE SOFT ONE.				
2	MAIN GALLEY - POT WASH	26	0	Yes	
A FEV	V PREVIOUSLY CLEANED PANS WERE FOUND SOILED WITH A GREASY RESIDUE.				
INSTR	RUCTED SANITATION OFFICER FOR PROPER SUPERVISION AND TRAINING OF THE	POTWASI	HERS AND TH	E GALLEY UTIL	ITIES.
3	CREW GALLEY	19	0	No	
REFRI	RVING SPOON WAS FOUND WITH THE HANDLE IN DIRECT CONTACT WITH THE GRAIGERATOR. RUCTED CREW GALLEY CHEF FOR PROPER SUPERVISION AND TRAINING OF THE C			SE IN THE REAG	CH-19N
4	POTABLE WATER	08	1	No	
THE T	IMES WHEN THE FREE CHLORINE RESIDUAL TESTS WERE PERFORMED WERE NOT	RECORD	ED IN THE PRO	DDUCTION LOG	
PROD	DUCTION LOG HAS BEEN CORRECTED ACORDING TO THE ABOVE INSTRUCTION.				
5	POTABLE WATER	08	1	No	
APPR	DISTANCE BETWEEN THE SAMPLE POINT AND THE CHLORINE INJECTION POINT ON OXIMATELY 1 FOOT.  SAMPLE POINT HAS BEEN MOVED 10 FEET FAR AWAY FROM THE CHLORINE INJECTION.			TON LINE WAS	
6	POTABLE WATER	08	1	No	
ENGIN	JE STRIPE WAS NOT PROVIDED ON THE POTABLE WATER LINE SUPPLYING THE SIINE ROOM. THE CLOSEST STRIPE WAS MORE THAN 5 METERS (15 FEET) AWAY.  WIND BLUE STRIPE IS PROVIDED ON THE POTABLE WATER LINE, SUPPLYING THE ABO			CHLORINE TAN	KS IN THE
7	POTABLE WATER	08	1	No	
A CON	MPREHENSIVE CROSS-CONNECTION CONTROL PROGRAM HAS NOT BEEN DEVELO	OPED FOR	R THIS VESSEI	L.	
	FENGINEER HAS ALREADY DEVELOPED THE COMPREHENSIVE CROSS-CONNECTION INTERPRETABLE FORM LEFT BY THE INSPECTORS.	ON CONTI	ROL ACCORDI	NG TO YOUR	
8	POTABLE WATER	08	1	No	
THE P	POTABLE WATER HOSES WERE NOT STORED CAPPED OR WITH THE ENDS COUPLE	D TOGET	HER.		
THE E	ENDS OF THE POTABLE WATER HOSES WERE COUPLED TOGETHER IMMEDEATELY	<b>/</b> .			
9	POTABLE WATER	08	1	No	
A BLU	JE STRIPE WAS NOT PROVIDED ON THE POTABLE WATER LINE IN THE POOL PUMP	ROOM.			
A NEV	V BLUE STRIPE IS PROVIDED ON THE POTABLE WATER IN THE POOL PUMP ROOM.				
11	POOL	10	0	No	
	IGTH OF ROPE 1.5 TIMES THE WIDTH OF THE POOL WAS NOT ATTACHED TO THE		ION DEVICE.		
A ROF	PE 1.5 TIMES THE WIDTH OF THE POOL IS ATTACHED TO THE FLOATATION DEVICE				
12	INTEGRATED PEST MANAGEMENT	40	0	No	
SHIPM WERE THE P	PESTICIDE SECTION OF THE INTEGRATED PEST MANAGEMENT PLAN WAS NOT UP T MENTS E NOT DOCUMENTED IN THE PLAN. PESTICIDE SECTION OF THE INTEGRATED PEST MANAGEMENT PLAN HAS BEEN UPI ECTIONS OF INCOMING SHIPMENTS HAS BEEN CREATED AND WILL BE USED FROM	DATED. A	NEW FORM CO	ONCERNING TH	
13	LIDO GALLEY	21	0	No	
THER	MOMETERS WERE NOT PROVIDED IN THE HOT CABINETS.				
AN OF	RDER FOR THE ABOVE MENTION THERMMOMETERS HAS BEEN ALREADY PLACED	).			

14 LIDO BUFFET 21 0 No SEVERAL OF THE GLASS SNEEZE SHIELDS WERE CHIPPED.

ALL THE CHIPPED GLASS SNEEZE SHIELDS WILL BE REPLACED WITH NEW ONES. RELEVANT ORDER HAS BEEN PLACED.

15 GARDEN LOUNGE BAR 30 0 No A "WASH HANDS OFTEN" SIGN WAS NOT POSTED OVER THE HANDWASH SINK.

A "WASH HANDS OF TEN" SIGN HAS BEEN POSTED OVER THE HANDWASH SINK.

Page 1 of 2DRAFT COPY

**DRAFT COPY** 

## 4/3/2003 **DETAILS OF INSPECTION VIOLATIONS**

## REF. POINTS CRITICAL DESCRIPTION NO. LOCATION

0

No

## **CORRECTIVE ACTION STATEMENT**

IN DEVELOPING THE CORRECTIVE ACTION STATEMENT FOR THIS INSPECTION, CRITICAL-ITEM DEFICIENCIES (DESIGNATED WITH YES IN CRITICAL COLUMN (WORTH 3 - 5 POINTS), WHETHER DEBITED OR NOT, SHOULD INCLUDE STANDARD OPERATING PROCEDURES AND MONITORING PROCÈDURES IMPLEMENTED TO PREVENT THE RECURRENCE OF THE CRITICAL DEFICIENCY.

PREPARE CORRECTIVE ACTION STATEMENT AS A WORD PROCESSING OR SPREADSHEET FILE WHICH WILL BE SENT TO USPHS / VSP AS AN

EMAIL MESSAGE ATTACHMENT. PLEASE EMAIL CORRECTIVE ACTION STATEMENT TO: VSP@CDC.GOV

USE EMAIL MESSAGE SUBJECT LINE: OLYMPIA EXPLORER - CAS - [04/03/2003] .

THE CORRECTIVE ACTION

CAPT. EVGENIOS MISAILIDIS MASTER AT SEA 7<sup>TH</sup> APRIL, 2003